

### **(Metal cutting- and CNC machinist A2) - Test**

*Find out the missing words. The first letter of the words is done.*

#### **The TRX55 PRO Vertical Milling Centre has**

1. a 40'' long work **t** \_\_\_\_\_.
2. an extended X- **a** \_\_\_\_\_ travel of 21.5''.
3. a 5HP **s** \_\_\_\_\_ spindle motor.
4. a 50-6000 RPM **s** \_\_\_\_\_.
5. a 12-tool automatic tool **c** \_\_\_\_\_ system.

#### **Metal cutting-and CNC machinists**

6. perform operations on CNC **I** \_\_\_\_\_ and mills.
7. produce **p** \_\_\_\_\_.
8. can use **c** \_\_\_\_\_ tools.
9. understand **t** \_\_\_\_\_ drawings.
10. perform traditional machine-based metal cutting, such as **t** \_\_\_\_\_, shaping, grinding, drilling and milling.

#### **In the cover letter you can write these sentences:**

11. I can handle manual metalworking **m** \_\_\_\_\_.
12. I enjoy working with surface **g** \_\_\_\_\_.
13. I can **o** \_\_\_\_\_ CNC mills.
14. I believe my **s** \_\_\_\_\_ and education make me suitable for the position.
15. I look **f** \_\_\_\_\_ to hearing from you.

#### **The following sentences are about industrial safety.**

##### **Employees**

16. must know and understand safety **s** \_\_\_\_\_.
17. must turn **o** \_\_\_\_\_ machines when they are not in use.
18. should wear **p** \_\_\_\_\_ clothing.
19. should read and understand the operator's **m** \_\_\_\_\_ before using the machines.
20. should wear safety **h** \_\_\_\_\_ to protect their heads from injury.