

Test for welders

Write **T** for true or **F** for false!

1. Heliarc is also called TIG welding and gas tungsten arc welding. ____
2. TIG welding is one of the few types of welding that can be done without any filler metal. ____
3. Using a gas tank is better performed outdoors. ____
4. TIG welding is really easy and advisable for starters. ____
5. TIG welding creates visually appealing welds and there is no spatter. ____
6. FCAW welding is really different from MIG welding.
7. For FCAW, the wire has a core of flux that creates a gas shield around the weld. ____
8. FCAW is better suited for thinner, lighter metals, because it is a high-heat welding method. ____
9. FCAW method creates a lot of waste. ____
10. FCAW method doesn't cost much. ____
11. A CV contains some personal information, work experience, education and personal skills. ____
12. In a cover letter you have to convince the employer that you are the most suitable applicant for the job. ____
13. You can't search for job advertisements on the Internet. ____
14. A welding area is very dangerous. ____
15. You can watch welding in progress. ____
16. You must keep several safety rules before, during and after welding. ____
17. Report any damage immediately to a technician. ____
18. Un-plug the welding machine when not in use. ____
19. UV welding flash to the skin or eyes doesn't cause any health problem.
20. After welding is finished, turn off the shielding gas at the regulator, turn off the machine and secure the hand piece safely.